U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved
OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing,
Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

	BRAY OIL COMPANY, INC. Corporate and Sales Offices	ECTION I (818)			
MANUFACTU	Have Moved to		EMERGENCY TELEPHONE NO		
BRAY OIL	2698 White Road Irvine, California 92714		(213) 575-1212		
ADDRESS (NL 9550 FLA	Phone (714) 850-1151	. CA 91731			
	e and synonyms Pluid	TRADE	E NAME AND SYNONYMS Brayco Licronic 756E		
Petroleum	LY	FORMULA	15.1-H-5606		

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	*	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS	•				•
HAZARDOUS MIXTURES	OF (OTHER LIC	DUIDS, SOLIDS, OR GASES	*	TLV (Units)
Non-hazardous as defined by U.S.	De	partmen	t of Labor 29CFR, Section 1915.2.		• •
		•			•
	•				

> 1.00°F	SPECIFIC GRAVITY (H20=1)	0.875
N/A	PERCENT, VOLATILE BY VOLUME (%)	N/A
N/A	EVAPORATION RATE	N/A
Insol.		
	N/A . N/A	N/A PERCENT, VOLATILE BY VOLUME (%) N/A EVAPORATION RATE (

SECTION IV - FIRE AND E	XPLOSION HAZARD DATA	•	
ASTA POINT (Method used) ASTA D92, COC 215°F	FLAMMABLE LIMITS. Not determined	Lei	Uel
EXTINGUISHING MEDIA Dry Chemical, Carbon Dioxide, Foam, Water SPECIAL FIRE FIGHTING PROCEDURES Do not use water except as fog, or spray t	Fog	nks to av	oid
heating above flash point.	30 0001 00 ma men 3 01 0a.		<u> </u>
UNUSUAL FIRE AND EXPLOSION HAZARDS Self-contained respiratory equipment when	fire fighting in confin	ed area.	

PAGE (1)

(Continued on reverse side)

Form OSHA-20 Rev. May 72

SECTION V - HEALTH HAZARD DATA THRESHOLD LIMIT VALUE Use 5 mg of oil mist in cubic meter of air. Not determined. EFFECTS OF OVEREXPOSURE Not expected to cause any ill effect except possibly in very sensitive individuals. May cause eye irritation. Avoid contact with eyes... EMERGENCY AND FIRST AID PROCEDURES Eye contact - flush thoroughly with water. Call physician. Skin contact - wash with soap and water. Ingestion - do not induce vomiting. Call physician.

STABILITY	UNSTABLE	1 :	CONDITIONS TO AVOID
•••	STABLE	Х	
HAZARDOUS DECO	OXIDIZING AG	CTS	
Combustion ma	<u>ay produce ca</u>	rbon mo	noxide and asphyxiants.
HAZARDOUS		R	CONDITIONS TO AVOID
HAZARDOUS POLYMERIZATION	MAY OCCU	r.	

SECTION VII - SPILL OR LEAK PROCEDURES STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Stop flow and shut off sources of ignition. Wipe or mop up, or absorb with clay, diatomaceous earth, or other inert material. Store in closed metal containers: WASTE DISPOSAL METHOD Controlled incineration or method in compliance with local, state, or federal regulations regarding health, air and water pollution.

•	- SECTION VIII - SPECIAL PR	ROTECTION IN	FORMATION
RESPIRATORY PRO None normall	y required except if oil mist	exceeds TLV	
VENTILATION	Only if oil mist exceeds TLV		SPECIAL
•	Only if oil mist exceeds TLV		OTHER
PROTECTIVE GLOV Plastic or R	ubber Gloves recommended	Safety glas	ses recommended.
OTHER PROTECTIV			

•	SECTION IX - SPECIAL PRECAUTIONS				
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Do not store near heat, open flame, or other sources of ignition.					
<u></u>					
OTHER PRECAUTIONS					

"The information presented herein has been compiled from sources PAGE (2) considered to be dependable and is accurate to the best of Form OSHA-20 GPO 930.540 seller's knowledge, however, seller makes no warranty whatsoever, expressed, implied, or of merchantability regarding the accuracy of such data or the results to be obtained from the use thereof. Seller assumes no responsibility for injury to buyer or to third persons or for any damage to any property and buyer assumes all such risks."

RJE-hp

bh/1.9June79